

CT-20

1893

OLD ST. EDMUND'S CHURCH (site)

Of frame construction this one story structure was three bays in length and three in depth. All exterior openings were lancet arched and contained sashed windows.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

St. Edmonds Church and Graveyard

(SITE)

AND/OR COMMON

2 LOCATION

STREET & NUMBER

Ponds Wood Road (Dalrymple Road)

CITY, TOWN

Chesapeake Beach

☒ VICINITY OF

CONGRESSIONAL DISTRICT

STATE

Maryland

COUNTY

Calvert

3 CLASSIFICATION

CATEGORY

☐ DISTRICT☐ BUILDING(S)☒ STRUCTURE☒ SITE☐ OBJECT

OWNERSHIP

☐ PUBLIC☐ PRIVATE☒ BOTH

PUBLIC ACQUISITION

☐ IN PROCESS☐ BEING CONSIDERED

STATUS

☒ OCCUPIED☐ UNOCCUPIED☐ WORK IN PROGRESS☒ ACCESSIBLE☐ YES: RESTRICTED☐ YES: UNRESTRICTED☐ NO

PRESENT USE

☐ AGRICULTURE☐ COMMERCIAL☐ EDUCATIONAL☐ ENTERTAINMENT☐ GOVERNMENT☐ INDUSTRIAL☐ MILITARY☐ MUSEUM☐ PARK☐ PRIVATE RESIDENCE☒ RELIGIOUS☐ SCIENTIFIC☐ TRANSPORTATION☐ OTHER:**4 OWNER OF PROPERTY**

NAME

Telephone #:

STREET & NUMBER

CITY, TOWN

☐ VICINITY OF

STATE, zip code

5 LOCATION OF LEGAL DESCRIPTIONCOURTHOUSE,
REGISTRY OF DEEDS, ETC.

Liber #: TBT 2

Folio #: 79

STREET & NUMBER

CITY, TOWN

STATE

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

CLVT-20

☐ FEDERAL ☒ STATE ☒ COUNTY ☐ LOCALDEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

CT-20

DEMOLISHED

CONDITION

☐ EXCELLENT
☐ GOOD
☐ FAIR

☐ DETERIORATED
☐ RUINS
☐ UNEXPOSED

CHECK ONE

☐ UNALTERED
☐ ALTERED

CHECK ONE

☐ ORIGINAL SITE
☐ MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The old St. Edmonds Church, c. 1893, no longer exists. In its place is a 1928 brick structure and a concrete block structure of more recent vintage. The old building was still standing when the 1967 survey was taken. (See Brinkman CLVT-20)

The brick building has a cornerstone dated September 28, 1928. It, too, has the pointed or stylized lancet arch windows. It has a clapboard steeple and rather old windows and doors that may have been taken from another structure.

On the east side of the church is a rather old graveyard with stones dating from the late 19th century. Some graves were so special as to be surrounded by an iron Victorian fence while others are marked with stones that have a name scratched in by hand.

As the accompanying photographs indicate, the 1928 brick structure appears to have been a brick veneer covering a clapboard structure, which is presumably the 1893 building. The process of demolition has made this structure a ruins with little left to record.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

CT-20

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 1400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE	COUNTY
STATE	COUNTY

11 FORM PREPARED BY

NAME / TITLE	
Wayne Nield II	
ORGANIZATION	DATE
Historic Sites Survey	
STREET & NUMBER	TELEPHONE
Prince Frederick, MD 20678	
CITY OR TOWN	STATE

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438

0500206527

1. STATE Maryland COUNTY Calvert TOWN VICINITY Sunderland STREET NO. ORIGINAL OWNER St. Edmond's Parish ORIGINAL USE Church PRESENT OWNER St. Edmond's Parish PRESENT USE deserted WALL CONSTRUCTION clapboard NO. OF STORIES 1 1/2		HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY 2. NAME St. Edmond's Church CT-20 DATE OR PERIOD 1893 (cornerstone) STYLE Victorian Gothic ARCHITECT BUILDER 3. FOR LIBRARY OF CONGRESS USE	
4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC no <p>This building is the old St. Edmond's Church now replaced by a nondescript 1930's structure of brick. This old one is clapboarded with 3 windows on each side, a protruding 3 sided nave on the back and a door and 2 windows in the front with a diamond shaped window in the pediment.</p> <p>The door is pointed in the Gothic style. The windows are clear glass and also pointed in the Gothic style. A cornerstone in the base gives the date as 1893. This building is a good example of the many small Methodist Chapels constructed in the Victorian style throughout the countryside in the late 19th century.</p>			
5. PHYSICAL CONDITION OF STRUCTURE Endangered Interior Exterior Deserted and falling into ruin.			
6. LOCATION MAP (Plan Optional)		7. PHOTOGRAPH	
8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.		9. NAME, ADDRESS AND TITLE OF RECORDER Paul A. Brinkman DATE OF RECORD July 17, 1967	

PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE

SUPPLEMENTAL INFORMATION AND PHOTOGRAPHS MAY BE ADDED ON SHEET OF SAME SIZE



CT-20





CT-20